

Pump Module Repair Report



Job #: Sample

Del. Ticket #: _____

Date In: _____

Date Out: _____

Houma Oilfield Pump Service Co., Inc.
221 N. Hollywood Rd. Houma, LA 70364
Ph: (985) 876-3171 www.houmaoilfieldpump.com

Customer: John Doe Drilling Rig: Ocean Jane PO #: _____

Repairs Ordered By: John Reference #: _____ Material Transfer #: _____

1	A-1700 Southwest triplex Module (2pc.)	
X	Discharge Cap Seat Gasket - Build Up & Bore	
X	Suction Cap Seat Gasket - Build Up & Bore	
X	Discharge Valve Seat - Build Up & Bore; Lap Valve Seats	
X	Suction Valve Seat - Build Up & Bore; Lap Valve Seats	
X	Wearplate Gasket - Build Up & Bore	
X	Wearplate Throat & Flat - Build Up & Bore	
X	Suction Port - Build Up & Bore	
X	Discharge Manifold Seal - Build Up & Bore	
	Suction Manifold Seal -	
	Cylinder Head Gasket -	
	Liner Gasket -	
X	Sandblast, Tap, Grease and Paint - & Install Studs	
	Stud Work -	
X	Cap (2), Flanges (2), & Liner Retainer Plate: Clean up & Inspect- OK	
X	Retainer Plugs (2): Clean & Inspect- Cracked Replace with NEW PLUGS (see materials furnished)	
Repairs Total:		\$

MATERIALS FURNISHED

24	4015-2 Valve Cover Studs & Nuts: \$ ea.	
8	4017-4 Liner Retainer Flange Socket Head Cap Screws: \$ ea.	
4	4016-3 Discharge Manifold Studs & Nuts: \$ ea.	
4	4016-96 Power End Studs & Nuts: \$ ea.	
6	3/4 x 2 1/2" Suction Manifold Cap Bolts with Lock Washers: \$ ea.	
2	4675-1A Retainer Plug: NEW \$ ea.	
1	Liner Retainer Nut: New \$ ea.	
2	P-129 Retainer Plug Gaskets: \$ ea.	

Materials Total:	\$
Total:	\$0.00

Inspected By: MLB3